HTS Terminals Support (as of Apr./2017)

| | HDV100 HDV130 | HDV230 | HDV330 | HDV430 | NTV | TGP600 | Bria (Softphone) | Media5-fone (Softphone) |
|--|------------------|--------|--------|--------|------|-------------|---------------------|----------------------------|
| Provisioning for plug and play | Yes | Yes | Yes | Yes | (NA) | (NA) | (NA) | (NA) |
| Phone Book on LCD of KX-HDV based on PBX speed dial | Yes | Yes | Yes | Yes | (NA) | (NA) | (NA) | (NA) |
| KX-HDV phone software version up from PBX | Yes | Yes | Yes | Yes | (NA) | (NA) | (NA) | (NA) |
| CO-Key | (NA) | Yes | (NA) | (NA) | (NA) | (NA) | (NA) | (NA) |
| Call Control | Yes | Yes | Yes | Yes | Yes | Yes (*1) | Yes (*2) | Yes (*3) |

^(*1) When TGP600 is installed under HTS LAN network, TGP's IP mode needs to be "Fixed IP" (= "DHCP" disabled). When it is installed at the other network, "DHCP" can be enabled.

^(*2) Video call is available but Call Hold and Call Transfer operations don't work.

^(*3) Video call is unavailable.