

Engineering Change Request

(Key Telephone System)

ECR No	SECECR-0670	Date issued	September 18, 2002
Proposed	Originated by <u>기안</u> <u>Minji Kim</u> Approved by <u>승3</u> <u>Steven Lee</u>		
Model	DCS	Unit	S/W ROM
Subject	S/W Version Upgrade to MP V7.06 & SP/ LP V7.1		
Summary of Change	1. [New Zealand] SVMi-8 problems are fixed. 2. [Sweden] PRI lock-up problem is fixed. 3. [UK] DDI calls to a UCD group display problem is fixed. 4. [Sweden] Calls to an unconditional UCD that overflow to AA group; AA port lock-up and Call drop problems are fixed. 5. Some problems are fixed.		
Reason for Change	To fix problems.		
Details of Change	Refer to 'Release Note' for V7.06		
Impact of Change	PTT: <i>No affected</i> Safety/EMC: <i>No affected</i> Classification: <i>On a running change basis</i>		
DOC affected	NONE		
Proposed Implementation Date		September, 2002	
TO	STUK & Europe, Australia, S.Africa, Israel, SEI		
Approval of ALE	Please sign here and return by FAX. Signature ALE Name Approval Authority Approval Number		

MODEL	EVEN1	ODD1	EVEN2	ODD2	CPM	LPM	BRI(E/O)		PRI(E/O)		PCMMC
CHKSUM	0EE4	9B10	42F2	3950	7762	275E	C791	B479	B082	5CAC	-
VERSION	V7.06				V7.1	V7.1	V3.4		V3.4		V7.04
DATE	020904				020218	020807	011106		011106		020610